FOR SALE: Repaired Rotax 914UL2 (115hp) Turbocharged Engine S/N 4417518

History:

Manufactured Feb 1997

TSN: 428

TSOH: 168 (overhauled by RRC in 1998 due to oil starvation event)

Current condition:

Engine was briefly submerged in fresh water (aircraft flipped on floats).

No evidence of water inside crankcase.

Engine has been completely torn down, inspected and reassembled using new bearings, seals & gaskets. Parts:

- New TCU
- New TCU wire harness (new style)
- New Wastegate servo motor
- New Ring mount (new style)
- New Airbox assy (new style with velocity stacks and sensor mounts)
- New cam and lifters
- New intake manifolds (new style)
- Serviceable crankshaft installed
- Carburetors replaced with newer overhauled carbs
- Starter overhauled
- New piston rings
- New rubber components
- New fuel pumps
- Overhauled overload clutch installed (engine was not previously equipped with clutch)

New 914UL2 price = \$26,995.00 USD

FOR SALE: \$21,995.00 USD