

|  | PART NO. | DESCRIPTION                        | REMARKS                              | RETAIL USD                       | CLA DISCOUNT |
|--|----------|------------------------------------|--------------------------------------|----------------------------------|--------------|
|    | 912UL    | 912UL 80hp ENGINE                  | \$200 Flat-rate insured shipping.    | \$14,871.00<br><i>July 2017!</i> | CALL         |
|    | 912ULS   | 912ULS 100hp ENGINE                | \$200 Flat-rate insured shipping.    | \$17,747.00<br><i>July 2017!</i> | CALL         |
|    | 912iS    | 912iS 100hp ENGINE (Fuel injected) | \$200 Flat-rate insured shipping.    | \$21,236.00<br><i>July 2017!</i> | CALL         |
|    | 914UL    | 914UL 115hp ENGINE (Turbocharged)  | \$200 Flat-rate insured shipping.    | \$28,469.00<br><i>July 2017!</i> | CALL         |
|    | 227 055  | SHIM 8.2x1.5                       | (for oil pressure)                   | \$0.66                           | CALL         |
|    | 241 785  | MAGNETIC DRAIN PLUG M12x1.5        |                                      | \$55.08                          | CALL         |
|   | 250 010  | GASKET RING C12x18                 | (for oil tank)                       | \$1.71                           | CALL         |
|  | 256 035  | AIR VENT LINE HOSE 120mm           | (5 yr. Rubber replacement)           | \$3.30                           | CALL         |
|  | 261 708  | FLOAT NEEDLE VALVE W. VITON TIP    |                                      | \$39.95                          | CALL         |
|  | 265 248  | SPARK PLUG CONNECTOR               | (5 yr. Rubber replacement)           | \$29.95                          | CALL         |
|  | 267 789  | RUBBER FLANGE                      | (5 yr. Rubber replacement)           | \$105.40                         | CALL         |
|  | 293 152  | ELECTRIC STARTER ASSY.             | Standard 914                         | \$752.30                         | CALL         |
|  | 295 410  | SERVO MOTOR                        |                                      | \$477.51                         | CALL         |
|  | 456 180  | OIL PRESSURE SENSOR M10x1          | (new replacement for Honeywell type) | \$249.84                         | CALL         |

|  |         |                                      |  |          |             |
|--|---------|--------------------------------------|--|----------|-------------|
|    | 660 771 | RUBBER BUFFER<br>10x15xM4            |  | \$27.78  | <b>CALL</b> |
|    | 825 016 | OIL FILTER                           | 10 x @ \$15.71                             | \$19.36  | <b>CALL</b> |
|    | 830 728 | GASKET, FLOAT<br>BOWL                |  | \$15.98  | <b>CALL</b> |
|    | 838 122 | COMPRESSION<br>SPRING L39.5          | (for oil pressure)                         | \$8.18   | <b>CALL</b> |
|    | 840 740 | NIPPLE 7/3.8                         | Fuel pump fitting for<br>1/4" ID tank line | \$14.96  | <b>CALL</b> |
|    | 850 965 | OIL SEAL 32x52x7                     |  | \$108.12 | <b>CALL</b> |
|    | 851 645 | SPRING TYPE CLAMP                    | (5 yr. Rubber<br>replacement)              | \$7.14   | <b>CALL</b> |
|   | 852 405 | SPRAG CLUTCH<br>HOUSING              |  | \$270.59 | <b>CALL</b> |
|  | 860 660 | HOSE 4x7 (per meter)                 | 914 carb vent to<br>airbox                 | \$88.17  | <b>CALL</b> |
|  | 860 710 | RUBBER BUFFER<br>25x20xm6            | (5 yr. Rubber<br>replacement)              | \$34.41  | <b>CALL</b> |
|  | 860 826 | RUBBER PLATE                         | (5 yr. Rubber<br>replacement)              | \$11.91  | <b>CALL</b> |
|  | 860 984 | AIR INTAKE HOSE<br>(turbo to airbox) | (5 yr. Rubber<br>replacement)              | \$56.53  | <b>CALL</b> |
|  | 860 985 | HOSE 4x7 (per meter)                 | (5 yr. Rubber<br>replacement)              | \$10.85  | <b>CALL</b> |
|  | 861 116 | DIAPHRAGM                            | (5 yr. Rubber<br>replacement)              | \$95.00  | <b>CALL</b> |
|  | 861 188 | FLOATs (Pair)                        |  | \$100.47 | <b>CALL</b> |

|  |         |   |                             |            |                 |
|--|---------|---|-----------------------------|------------|-----------------|
|    | 861 640 | BENT TUBE ASSY.                         |                             | \$43.16    | <b>CALL</b>     |
| No Photo   | 864 250 | Wire Ass'y Oil Pressure Sensor          | (required with 456 180)     | \$109.92   | <b>CALL</b>     |
|    | 865 710 | IGNITION CABLE 7mm (per meter)          |                             | \$35.37    | <b>CALL</b>     |
|    | 881 360 | FUEL PUMP SET (replaces 893110, 893115) | (5 yr. Rubber replacement)  | \$173.00   | <b>CALL</b>     |
|    | 887 254 | ALTERNATOR SET                          | (limited supply)            | \$1,690.12 | <b>1,056.87</b> |
| No Photo   | 889 536 | CARB OVERHAUL KIT (for one carb only)   |                             | \$325.99   | <b>CALL</b>     |
|    | 892 520 | C.D. CARB 914 1/3                       |                             | \$1,426.96 | <b>CALL</b>     |
|   | 892 525 | C.D. CARB 914 2/4                       |                             | \$1,523.61 | <b>CALL</b>     |
|  | 892 530 | C.D. CARB 912 1/3                       |                             | \$1,026.77 | <b>CALL</b>     |
|  | 892 535 | C.D. CARB 912 2/4                       |                             | \$1,026.77 | <b>CALL</b>     |
|  | 897 941 | CABLE BOWDEN ASSY.                      |                             | \$77.53    | <b>CALL</b>     |
|  | 922 070 | RADIATOR CAP                            | New 1.2 bar cap with gasket | \$69.95    | <b>CALL</b>     |
|  | 922 192 | WATER TUBE 90 DEG 17 mm ID              | (5 yr. Rubber replacement)  | \$52.93    | <b>CALL</b>     |
|  | 922 250 | WATER TUBE 17/100 (per meter)           | (5 yr. Rubber replacement)  | \$39.95    | <b>CALL</b>     |
|  | 922 665 | EXPANSION TANK ASSY                     |                             | \$351.21   | <b>CALL</b>     |

|  |         |                                      |   |            |             |
|--|---------|--------------------------------------|---|------------|-------------|
|    | 938 287 | RETURN SPRING,<br>CHOKE              |   | \$12.44    | <b>CALL</b> |
|    | 938 289 | RETURN SPRING,<br>THROTTLE           |   | \$14.26    | <b>CALL</b> |
|    | 940 558 | HOSE NIPPLE M6                       |   | \$16.70    | <b>CALL</b> |
|    | 940 873 | BANJO BOLT<br>M10x1x30               | (914 oil pump)                                | \$16.26    | <b>CALL</b> |
|    | 940 879 | BANJO BOLT<br>M16x1.5x28             | (for crankcase)                               | \$23.94    | <b>CALL</b> |
|    | 956 314 | HOSE NIPPLE 10                       |   | \$23.81    | <b>CALL</b> |
|    | 958 856 | SPRAG CLUTCH<br>51.710x68.377x13     |   | \$361.07   | <b>CALL</b> |
|   | 960 060 | RUBBER BUFFER<br>25x15xm6            | (5 yr. Rubber<br>replacement)                 | \$28.81    | <b>CALL</b> |
|  | 961 215 | JET NEEDLE                           |   | \$16.34    | <b>CALL</b> |
|  | 965 349 | RECTIFIER<br>REGULATOR               |   | \$175.56   | <b>CALL</b> |
|  | 965 444 | ADVANCED START<br>MODULE (ASM) 6+6+1 | (also 965446<br>4-Pin modules.<br>Same price) | \$931.12   | <b>CALL</b> |
|  | 965 531 | TEMPERATURE<br>SENSOR M10x1.5        |   | \$195.25   | <b>CALL</b> |
|  | 966 741 | TURBO CONTROL<br>UNIT TLR 4.6        | (limited supply)                              | \$2,824.79 | <b>CALL</b> |
|  | 966 872 | FLYWHEEL HUB                         | Retarded for<br>"soft start" ignition         | \$357.05   | <b>CALL</b> |
|  | 996 738 | 914 FUEL PUMP                        |   | \$356.23   | <b>CALL</b> |

|  |         |   |  |            |                   |
|--|---------|---|--|------------|-------------------|
|    | 996 947 | CARB GASKET SET<br>(two carbs)              |  | \$109.90   | <b>CALL</b>       |
|    | ASKIT   | ADVANCED START Kit<br>(4-Pin to 6-Pin etc.) | Incl. AS trigger<br>Hub, 2 x 6-pin<br>AS Modules | \$4,880.00 | <b>\$3,300.00</b> |
|    | BHEXH   | 914 EXHAUST KIT<br>(latest Rotax updates)   | (limited supply)                                 | \$4,585.47 | <b>CALL</b>       |
|    | PJA-08  | FIRE SLEEVE 1/2" ID<br>(per foot)           |  | \$7.95     | <b>CALL</b>       |
|    | PJA-10  | FIRE SLEEVE 5/8" ID<br>(per foot)           |  | \$8.50     | <b>CALL</b>       |
|    | PJA-12  | FIRE SLEEVE 7/8" ID<br>(per foot)           |  | \$12.50    | <b>CALL</b>       |
|    | RU0870  | 914 AIR FILTER 3"<br>62mm offset flange     |  | \$41.95    | <b>CALL</b>       |
|  | SHC     | HEAT COMPOUND<br>(Wacker P-12, 6 gm)        | (from 897 186)                                   | \$6.22     | <b>CALL</b>       |
|  | SP2704  | 912 Air Filter                              |  | \$34.95    | <b>CALL</b>       |

DISCOUNT PRICING FOR OUR STS KIT BUILDERS

PRICING SUBJECT TO CHANGE WITHOUT NOTICE

*Canadian Light Amphibians*

Bus: 705 481-1817 Cell: 705 279-5243 email: [SeareyCanada@gmail.com](mailto:SeareyCanada@gmail.com)