











	<b>PART NO.</b>	<b>DESCRIPTION</b>	<b>REMARKS</b>	<b>RETAIL USD</b>	<b>CLA DISCOUNT</b>
	912UL	912UL 80hp ENGINE	\$200 Flat-rate insured shipping.	\$16,505.00	<b>CALL</b>
	912ULS	912ULS 100hp ENGINE	\$200 Flat-rate insured shipping.	\$19,701.00	<b>CALL</b>
	912iS	912iS 100hp ENGINE (Fuel injected)	\$200 Flat-rate insured shipping.	\$23,284.00	<b>CALL</b>
	914UL	914UL 115hp ENGINE (Turbocharged)	\$200 Flat-rate insured shipping.	\$31,539.00	<b>CALL</b>
	915iS	915iS 141hp ENGINE (Turbo Fuel injected)	\$200 Flat-rate insured shipping.	\$38,667.00	<b>CALL</b>
	227 055	SHIM 8.2x1.5	(for oil pressure)	\$0.66	<b>CALL</b>
	241 785	MAGNETIC DRAIN PLUG M12x1.5		\$55.73	<b>CALL</b>
	250 010	GASKET RING C12x18	(for oil tank)	\$1.71	<b>CALL</b>
	256 035	AIR VENT LINE HOSE 120mm	(5 yr. Rubber replacement)	\$2.46	<b>CALL</b>
	261 708	FLOAT NEEDLE VALVE W. VITON TIP		\$59.07	<b>CALL</b>
	265 248	SPARK PLUG CONNECTOR	(5 yr. Rubber replacement)	\$16.80	<b>CALL</b>
	267 789	RUBBER FLANGE	(5 yr. Rubber replacement)	\$105.40	<b>CALL</b>
	293 152	ELECTRIC STARTER ASSY.	Standard 914	\$752.30	<b>CALL</b>
	295 410	SERVO MOTOR		\$477.51	<b>CALL</b>

	456 180	OIL PRESSURE SENSOR M10x1	(new replacement for Honeywell type)	\$249.84	<b>CALL</b>
	660 771	RUBBER BUFFER 10x15xM4		\$27.78	<b>CALL</b>
	825 016	OIL FILTER	10 x @ \$15.71	\$19.36	<b>CALL</b>
	830 728	GASKET, FLOAT BOWL		\$15.98	<b>CALL</b>
	838 122	COMPRESSION SPRING L39.5	(for oil pressure)	\$8.18	<b>CALL</b>
	840 740	NIPPLE 7/3.8	Fuel pump fitting for 1/4" ID tank line	\$14.96	<b>CALL</b>
	850 965	OIL SEAL 32x52x7		\$108.12	<b>CALL</b>
	851 645	SPRING TYPE CLAMP	(5 yr. Rubber replacement)	\$7.14	<b>CALL</b>
	852 405	SPRAG CLUTCH HOUSING		\$289.85	<b>CALL</b>
	860 660	HOSE 4x7 (per meter)	914 carb vent to airbox	\$88.17	<b>CALL</b>
	860 710	RUBBER BUFFER 25x20xm6	(5 yr. Rubber replacement)	\$34.41	<b>CALL</b>
	860 826	RUBBER PLATE	(5 yr. Rubber replacement)	\$11.91	<b>CALL</b>
	860 984	AIR INTAKE HOSE (turbo to airbox)	(5 yr. Rubber replacement)	\$56.53	<b>CALL</b>
	860 985	HOSE 4x7 (per meter)	(5 yr. Rubber replacement)	\$10.85	<b>CALL</b>
	861 116	DIAPHRAGM	(5 yr. Rubber replacement)	\$95.00	<b>CALL</b>

	861 188	FLOATs (Pair)		\$150.95	<b>CALL</b>
	861 640	BENT TUBE ASSY.		\$43.16	<b>CALL</b>
	864 250	Wire Ass'y Oil Pressure Sensor	(required with 456 180)	\$109.92	<b>CALL</b>
	865 710	IGNITION CABLE 7mm (per meter)		\$35.37	<b>CALL</b>
	887 254	ALTERNATOR SET	(limited supply)	\$1,690.12	<b>1,056.87</b>
	889 536	CARB OVERHAUL KIT (for one carb only)		\$226.99	<b>CALL</b>
	892 520	C.D. CARB 914 1/3	Used serviceable also available	\$1,426.96	<b>CALL</b>
	892 525	C.D. CARB 914 2/4	Used serviceable also available	\$1,523.61	<b>CALL</b>
	892 530	C.D. CARB 912s 1/3		\$1,026.77	<b>CALL</b>
	892 535	C.D. CARB 912s 2/4		\$1,026.77	<b>CALL</b>
	893 115	FUEL PUMP SET (replaces 893110, 881360)	(5 yr. Rubber replacement)	\$173.00	<b>CALL</b>
	897 941	CABLE BOWDEN ASSY.		\$77.53	<b>CALL</b>
	922 070	RADIATOR CAP	New 1.2 bar cap with gasket	\$69.95	<b>CALL</b>
	922 192	WATER TUBE 90 DEG 17 mm ID	(5 yr. Rubber replacement)	\$52.93	<b>CALL</b>
	922 250	WATER TUBE 17/100 (per meter)	(5 yr. Rubber replacement)	\$61.02	<b>CALL</b>

	922 665	EXPANSION TANK ASSY		\$314.63	CALL
	938 287	RETURN SPRING, CHOKE		\$12.44	CALL
	938 289	RETURN SPRING, THROTTLE		\$14.26	CALL
	940 558	HOSE NIPPLE M6		\$16.70	CALL
	940 873	BANJO BOLT M10x1x30	(914 oil pump)	\$16.26	CALL
	940 879	BANJO BOLT M16x1.5x28	(for crankcase)	\$23.94	CALL
	956 314	HOSE NIPPLE 10		\$23.81	CALL
	958 856	SPRAG CLUTCH 51.710x68.377x13		\$312.14	CALL
	960 060	RUBBER BUFFER 25x15xm6	(5 yr. Rubber replacement)	\$28.81	CALL
	961 215	JET NEEDLE		\$16.34	CALL
	965 349	RECTIFIER REGULATOR		\$147.57	CALL
	965 444	ADVANCED START MODULE (ASM) 6+6+1	(also 965446 4-Pin modules. Same price)	\$1,016.66	CALL
	965 531	TEMPERATURE SENSOR M10x1.5		\$195.25	CALL
	966 741	TURBO CONTROL UNIT TLR 4.6	(limited supply)	\$2,824.79	CALL
	966 872	FLYWHEEL HUB	Retarded for "soft start" ignition	\$367.76	CALL

	996 738	914 FUEL PUMP		\$356.23	<b>CALL</b>
	996 947	CARB GASKET SET (two carbs)		\$103.46	<b>CALL</b>
	ASKIT	ADVANCED START Kit (4-Pin to 6-Pin etc.)	Incl. AS trigger Hub, 2 x 6-pin AS Modules	\$4,880.00	<b>\$3,300.00</b>
	BHEXH	914 EXHAUST KIT (latest Rotax updates)	(limited supply)	\$4,585.47	<b>CALL</b>
	PJA-08	FIRE SLEEVE 1/2" ID (per foot)		\$7.95	<b>CALL</b>
	PJA-10	FIRE SLEEVE 5/8" ID (per foot)		\$8.50	<b>CALL</b>
	PJA-12	FIRE SLEEVE 7/8" ID (per foot)		\$12.50	<b>CALL</b>
	RU0870	914 AIR FILTER 3" 62mm offset flange		\$41.95	<b>CALL</b>
	SHC	HEAT COMPOUND (Wacker P-12, 6 gm)	(from 897 186)	\$6.22	<b>CALL</b>
	SP2704	912 Air Filter		\$34.95	<b>CALL</b>

DISCOUNT PRICING FOR OUR STS KIT BUILDERS

PRICING SUBJECT TO CHANGE WITHOUT NOTICE

*Canadian Light Amphibians*

Bus: 705 481-1817 Cell: 705 279-5243 email: [SeareyCanada@gmail.com](mailto:SeareyCanada@gmail.com)